

Setra

Garanti: 12 ay
Bu ürüne ait Türkiye içi kapı teslim fiyat ve teslim süresi içeren teklifimizi almak için **info@yursat.com.tr** e-posta adresine başvuru yapabilir ya da ayrıntılı bilgi için +90 224 240 03 04 numaralı telefonumuzdan bizlere ulaşabilirsiniz.
Setra Markası, tedarik süresi için lütfen bizimle iletişime geçiniz.

Firmamız Setra Türkiye Distribütörü veya temsilcisi değildir. Firmamız sipariş durumunda, belirtilen ürünlerde sadece Orjinal ve yeni ürün teklifi sunmaktadır. Bu sitede gösterilen Özel marka adları ve ticari markalar ilgili sahiplerinin mülkiyetindedir, talep durumunda kaldırılmaktadır.



Ürün	Açıklama
Srpm-001wb-V1-E	ROOM PRESSURE MONITOR
1411-004-A-B-2s-Xx-02-6	HIGH OUTPUT LINEAR ACCELEROMETER
1411-015-A-B-2s-25-02-6	HIGH OUTPUT LINEAR ACCELEROMETER
1411-002-A-B-Bt-10-02-7	HIGH OUTPUT LINEAR ACCELEROMETER
1411-002-A-B-Bt-Xx-02-N	HIGH OUTPUT LINEAR ACCELEROMETER
2701-005p-G-1f-3b-02-Y-F	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE PRESSURE TRANSDUCER
Srpm-R05wb-V1-V	ROOM PRESSURE MONITOR
1411-004-A-B-Bt-25-02-N	HIGH OUTPUT LINEAR ACCELEROMETER
1411-008-A-B-2s-Xx-02-7	HIGH OUTPUT LINEAR ACCELEROMETER
2701-010p-A-1f-3b-02-N-F	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE PRESSURE TRANSDUCER
1411-008-A-B-2s-02-02-3	HIGH OUTPUT LINEAR ACCELEROMETER

Model 231rs	
327358 5203005	
2701-005p-G-1f-3b-10-N-F	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE PRESSURE TRANSDUCER
1411-004-A-B-2s-02-02-N	HIGH OUTPUT LINEAR ACCELEROMETER
1411-004-A-B-2s-Xx-02-7	HIGH OUTPUT LINEAR ACCELEROMETER
1411-004-A-B-Bt-10-02-N	HIGH OUTPUT LINEAR ACCELEROMETER
1411-004-A-B-Bt-10-02-3	HIGH OUTPUT LINEAR ACCELEROMETER
2701-010p-G-1f-2b-10-N-F	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE PRESSURE TRANSDUCER
1411-015-A-B-2s-25-02-3	HIGH OUTPUT LINEAR ACCELEROMETER
2671-#-W-D-#-A1-C-N	
26410r1wd11a1c	
1411-004-A-B-2s-10-02-6	HIGH OUTPUT LINEAR ACCELEROMETER
Srpm-R05wb-A2-E	ROOM PRESSURE MONITOR
2601# #	
1411-004-A-B-Bt-02-02-N	HIGH OUTPUT LINEAR ACCELEROMETER
1411-015-A-B-2s-02-02-7	HIGH OUTPUT LINEAR ACCELEROMETER
2701-010p-G-1f-2b-10-Y-F	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE PRESSURE TRANSDUCER
2901-060-P-G-T6-11-15-3-N	PRESSURE TRANSDUCER 1 1/2IN TRI 0/30PSI 15IN
1411-004-A-B-Bt-10-02-7	HIGH OUTPUT LINEAR ACCELEROMETER
1411-002-A-B-2s-Xx-02-3	HIGH OUTPUT LINEAR ACCELEROMETER
1411-008-A-B-2s-25-02-6	HIGH OUTPUT LINEAR ACCELEROMETER
Model 239	
2701-010p-A-1f-3b-02-Y-F	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE PRESSURE TRANSDUCER
1411-008-A-B-2s-25-02-N	HIGH OUTPUT LINEAR ACCELEROMETER
231g-MS1-3v-D	WET TO WET DIFFERENTIAL, MULTI CONFIGURABLE PRESSURE TRANSDUCER
1411-008-A-B-2s-Xx-02-N	HIGH OUTPUT LINEAR ACCELEROMETER
2641-0r1wd-11-A1-C	
	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE

2701-005p-A-1f-2b-02-Y-F	PRESSURE TRANSDUCER
1411-008-A-B-2s-Xx-02-6	HIGH OUTPUT LINEAR ACCELEROMETER
2701-005p-A-1f-3b-10-N-F	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE PRESSURE TRANSDUCER
1411-004-A-B-Bt-Xx-02-7	HIGH OUTPUT LINEAR ACCELEROMETER
1411-008-A-B-2s-10-02-3	HIGH OUTPUT LINEAR ACCELEROMETER
1411-015-A-B-2s-10-02-N	HIGH OUTPUT LINEAR ACCELEROMETER
1411-002-A-B-Bt-02-02-6	HIGH OUTPUT LINEAR ACCELEROMETER
2701-010p-A-1f-2b-10-Y-F	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE PRESSURE TRANSDUCER
2701-010p-A-1f-2b-10-N-F	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE PRESSURE TRANSDUCER
730g100tan12cd9k	
2301-#-3v-11-# #	
C264	
Mrc-C-S-C	
Sn:59253	
1411-008-A-B-Bt-Xx-02-6	HIGH OUTPUT LINEAR ACCELEROMETER
1411-004-A-B-2s-25-02-7	HIGH OUTPUT LINEAR ACCELEROMETER
205-2	
1411-004-A-B-2s-10-02-7	HIGH OUTPUT LINEAR ACCELEROMETER
2701-005p-A-1f-2b-10-Y-F	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE PRESSURE TRANSDUCER
2701-010p-G-1f-3b-10-Y-F	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE PRESSURE TRANSDUCER
1411-004-A-B-2s-02-02-7	HIGH OUTPUT LINEAR ACCELEROMETER
Model 141a; Range +/- 60g	
Model 141a; Range +/- 15g	
2701-010p-A-1f-3b-10-Y-F	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE PRESSURE TRANSDUCER
1411-008-A-B-2s-02-02-6	HIGH OUTPUT LINEAR ACCELEROMETER
1411-002-A-B-Bt-25-02-7	HIGH OUTPUT LINEAR ACCELEROMETER
1411-002-A-B-Bt-02-02-3	HIGH OUTPUT LINEAR ACCELEROMETER

1411-002-A-B-Bt-10-02-N 2091030hbg411h1de1	HIGH OUTPUT LINEAR ACCELEROMETER
Srpm-0r1wb-V1-E	ROOM PRESSURE MONITOR
2671-#-W-D-#-A1-G-N	
2701-005p-A-1f-2b-10-N-F	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE PRESSURE TRANSDUCER
2671005-W-D11-1k-Cn	
2701-005p-G-1f-3b-10-Y-F	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE PRESSURE TRANSDUCER
2701-600m-A-1f-3b-02-N-F	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE PRESSURE TRANSDUCER
1411-008-A-B-2s-10-02-N	HIGH OUTPUT LINEAR ACCELEROMETER
1411-015-A-B-2s-10-02-3	HIGH OUTPUT LINEAR ACCELEROMETER
1411-002-A-B-Bt-Xx-02-6	HIGH OUTPUT LINEAR ACCELEROMETER
231g-#-#-N	
2691-#-11-#-#-#-N	
1411-002-A-B-Bt-Xx-02-3	HIGH OUTPUT LINEAR ACCELEROMETER
1411-008-A-B-Bt-25-02-6	HIGH OUTPUT LINEAR ACCELEROMETER
Srpm-0r1wb-A2-E	ROOM PRESSURE MONITOR
Srpm-0r5wb-V1-E	ROOM PRESSURE MONITOR
1411-008-A-B-Bt-10-02-6	HIGH OUTPUT LINEAR ACCELEROMETER
1411-015-A-B-2s-02-02-N	HIGH OUTPUT LINEAR ACCELEROMETER
2701-005p-G-1f-2b-10-N-F	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE PRESSURE TRANSDUCER
2641-#-#-T1-#	
2701-005p-G-1f-2b-02-N-F	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE PRESSURE TRANSDUCER
2301-#-3v-2e-#-#	
1411-008-A-B-Bt-25-02-N	HIGH OUTPUT LINEAR ACCELEROMETER
1411-015-A-B-2s-10-02-7	HIGH OUTPUT LINEAR ACCELEROMETER
1411-004-A-B-Bt-25-02-7	HIGH OUTPUT LINEAR ACCELEROMETER
2701-600m-A-1f-2b-02-N-F	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE PRESSURE TRANSDUCER
1411-004-A-B-Bt-Xx-02-3	HIGH OUTPUT LINEAR ACCELEROMETER

1411-002-A-B-Bt-25-02-6	HIGH OUTPUT LINEAR ACCELEROMETER
2701-010p-A-1f-2b-02-Y-F	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE PRESSURE TRANSDUCER
1411-008-A-B-2s-02-02-N	HIGH OUTPUT LINEAR ACCELEROMETER
2651-#-#-A1-#	
2701-005p-A-1f-3b-02-Y-F	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE PRESSURE TRANSDUCER
2701-010p-G-1f-3b-02-N-F	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE PRESSURE TRANSDUCER
2641 050lb 2d T1 F	
1411-004-A-B-2s-10-02-3	HIGH OUTPUT LINEAR ACCELEROMETER
1411-008-A-B-Bt-25-02-7	HIGH OUTPUT LINEAR ACCELEROMETER
1411-008-A-B-2s-Xx-02-3	HIGH OUTPUT LINEAR ACCELEROMETER
1411-002-A-B-Bt-25-02-3	HIGH OUTPUT LINEAR ACCELEROMETER
206108-10-Gyr2	
1411-008-A-B-Bt-02-02-6	HIGH OUTPUT LINEAR ACCELEROMETER
1411-008-A-B-2s-10-02-6	HIGH OUTPUT LINEAR ACCELEROMETER
1411-015-A-B-2s-10-02-6	HIGH OUTPUT LINEAR ACCELEROMETER
1411-004-A-B-Bt-02-02-6	HIGH OUTPUT LINEAR ACCELEROMETER
2701-005p-A-1f-2b-02-N-F	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE PRESSURE TRANSDUCER
2671-#-W-#-#-A1-H-D	
2701-005p-A-1f-3b-02-N-F	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE PRESSURE TRANSDUCER
231g-MS2-3v-D	WET TO WET DIFFERENTIAL, MULTI CONFIGURABLE PRESSURE TRANSDUCER
2671-#-W-D-#-Ap-G-N	
2701-010p-G-1f-2b-02-N-F	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE PRESSURE TRANSDUCER
1411-008-A-B-Bt-02-02-N	HIGH OUTPUT LINEAR ACCELEROMETER
1411-002-A-B-Bt-Xx-02-7	HIGH OUTPUT LINEAR ACCELEROMETER
206-106nbc/10-450	
Srpm-0r5wb-A1-E	ROOM PRESSURE MONITOR
	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE

2701-600m-A-1f-3b-10-Y-F	PRESSURE TRANSDUCER
2701-600m-A-1f-2b-02-Y-F	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE PRESSURE TRANSDUCER
231g-##-D	
1411-002-A-B-Bt-02-02-N	HIGH OUTPUT LINEAR ACCELEROMETER
1411-008-A-B-2s-10-02-7	HIGH OUTPUT LINEAR ACCELEROMETER
1411-002-A-B-2s-Xx-02-N	HIGH OUTPUT LINEAR ACCELEROMETER
1411-015-A-B-2s-02-02-3	HIGH OUTPUT LINEAR ACCELEROMETER
1411-004-A-B-Bt-10-02-6	HIGH OUTPUT LINEAR ACCELEROMETER
1411-002-A-B-Bt-10-02-6	HIGH OUTPUT LINEAR ACCELEROMETER
2671-#-W-#-#-Ap-H-D	
1411-002-A-B-2s-Xx-02-6	HIGH OUTPUT LINEAR ACCELEROMETER
Srpm-2r5wb-A2-E	ROOM PRESSURE MONITOR
1411-004-A-B-2s-10-02-N	HIGH OUTPUT LINEAR ACCELEROMETER
1411-002-A-B-Bt-10-02-3	HIGH OUTPUT LINEAR ACCELEROMETER
730g010tan12cd9k	
1411-004-A-B-2s-Xx-02-3	HIGH OUTPUT LINEAR ACCELEROMETER
Set-Cr209m-3kp	
1411-008-A-B-2s-25-02-3	HIGH OUTPUT LINEAR ACCELEROMETER
1411-004-A-B-Bt-Xx-02-N	HIGH OUTPUT LINEAR ACCELEROMETER
1411-004-A-B-2s-Xx-02-N	HIGH OUTPUT LINEAR ACCELEROMETER
1411-002-A-B-Bt-25-02-N	HIGH OUTPUT LINEAR ACCELEROMETER
1411-004-A-B-Bt-02-02-3	HIGH OUTPUT LINEAR ACCELEROMETER
100pa-2f-2b-02-W-Dn	
2301-#-2f-#-#-#	
1411-004-A-B-Bt-25-02-3	HIGH OUTPUT LINEAR ACCELEROMETER
1411-004-A-B-2s-02-02-6	HIGH OUTPUT LINEAR ACCELEROMETER
2641-#-#-A1-#	
1411-008-A-B-2s-02-02-7	HIGH OUTPUT LINEAR ACCELEROMETER
1411-008-A-B-Bt-02-02-3	HIGH OUTPUT LINEAR ACCELEROMETER
Srpm-R25wb-A1-E	ROOM PRESSURE MONITOR

2701-010p-G-1f-2b-02-Y-F	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE PRESSURE TRANSDUCER
1411-008-A-B-Bt-10-02-N	HIGH OUTPUT LINEAR ACCELEROMETER
1411-004-A-B-2s-25-02-3	HIGH OUTPUT LINEAR ACCELEROMETER
1411-004-A-B-2s-02-02-3	HIGH OUTPUT LINEAR ACCELEROMETER
2701-010p-G-1f-3b-10-N-F	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE PRESSURE TRANSDUCER
Srpm-0r1wb-A1-E	ROOM PRESSURE MONITOR
1411-008-A-B-2s-25-02-7	HIGH OUTPUT LINEAR ACCELEROMETER
2701-600m-A-1f-2b-10-Y-F	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE PRESSURE TRANSDUCER
Model 231	
1411-002-A-B-Bt-02-02-7	HIGH OUTPUT LINEAR ACCELEROMETER
Srpm-2r5wb-V1-E	ROOM PRESSURE MONITOR
2701-005p-A-1f-3b-10-Y-F	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE PRESSURE TRANSDUCER
2701-600m-A-1f-3b-02-Y-F	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE PRESSURE TRANSDUCER
2701-010p-G-1f-3b-02-Y-F	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE PRESSURE TRANSDUCER
2701-005p-G-1f-2b-10-Y-F	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE PRESSURE TRANSDUCER
1411-008-A-B-Bt-10-02-7	HIGH OUTPUT LINEAR ACCELEROMETER
2701-600m-A-1f-3b-10-N-F	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE PRESSURE TRANSDUCER
2701-010p-A-1f-3b-10-N-F	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE PRESSURE TRANSDUCER
2671-#-W-D-#-Ap-C-N	
1411-008-A-B-Bt-Xx-02-N	HIGH OUTPUT LINEAR ACCELEROMETER
Model 264	
2701-010p-A-1f-2b-02-N-F	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE PRESSURE TRANSDUCER
1411-008-A-B-Bt-Xx-02-7	HIGH OUTPUT LINEAR ACCELEROMETER
1411-015-A-B-2s-02-02-6	HIGH OUTPUT LINEAR ACCELEROMETER
1411-008-A-B-Bt-Xx-02-3	HIGH OUTPUT LINEAR ACCELEROMETER

1411-004-A-B-Bt-Xx-02-6	HIGH OUTPUT LINEAR ACCELEROMETER
239108-Sp	PRESSURE TRANSDUCER 24VDC 4-20MA
2301-#-3v-2d-# #	
2701-005p-G-1f-2b-02-Y-F	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE PRESSURE TRANSDUCER
1411-002-A-B-2s-Xx-02-7	HIGH OUTPUT LINEAR ACCELEROMETER
1411-008-A-B-Bt-02-02-7	HIGH OUTPUT LINEAR ACCELEROMETER
264	
1411-004-A-B-Bt-25-02-6	HIGH OUTPUT LINEAR ACCELEROMETER
1411-008-A-B-Bt-10-02-3	HIGH OUTPUT LINEAR ACCELEROMETER
2701-005p-G-1f-3b-02-N-F	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE PRESSURE TRANSDUCER
1411-008-A-B-Bt-25-02-3	HIGH OUTPUT LINEAR ACCELEROMETER
2651-#-#-T1-#	
1411-004-A-B-2s-25-02-N	HIGH OUTPUT LINEAR ACCELEROMETER
1411-004-A-B-2s-25-02-6	HIGH OUTPUT LINEAR ACCELEROMETER
1411-004-A-B-Bt-02-02-7	HIGH OUTPUT LINEAR ACCELEROMETER
2701-600m-A-1f-2b-10-N-F	SETRACERAM FOR BAROMETRIC GAUGE OR ABSOLUTE PRESSURE TRANSDUCER