

Vaisala

Garanti: 12 ay
Bu ürüne ait Türkiye içi kapı teslim fiyat ve teslim süresi içeren teklifimizi almak için info@yursat.com.tr e-posta adresine başvuru yapabilir ya da ayrıntılı bilgi için +90 224 240 03 04 numaralı telefonumuzdan bizlere ulaşabilirsiniz.
Vaisala Markası, tedarik süresi için lütfen bizimle iletişime geçiniz.

Firmamız Vaisala Türkiye Distribütörü veya temsilcisi değildir. Firmamız sipariş durumunda, belirtilen ürünlerde sadece Orjinal ve yeni ürün teklifi sunmaktadır. Bu sitede gösterilen Özel marka adları ve ticari markalar ilgili sahiplerinin mülkiyetindedir, talep durumunda kaldırılmaktadır.



Ürün	Açıklama
WSP150	Vaisala Surge Protector no Connectors A compact transient over-voltage suppressor designed for outdoor use. It can provide over-voltage protection for 2 power supply lines and RS-422, RS-485, RS-232 serial communication or 2 mA loop lines. It can be used with WXT530 series, WXT520 and WXT510, WMT700 (non-heated), WA15 Wind Set, WM30 Wind Set, DSC211, and DST111. Also other instruments can be protected if the current consumption is less than 1.5A. Install WSP150 close to the protected instrument (maximum 3 m). Vaisala recommends using surge protectors if: • Your weather instruments are installed in areas with an elevated risk of lightning strike, such as on top of high buildings or masts, or in open areas • Your cable length exceeds 10 m • You have unshielded, open-wire lines
WXTPTUSP	WXTPTU-Module Spare Part PTU-Module Spare Part for the WXT530 series. Compatible with WXT520 and WXT510
WXT530	6U1B2A3D2B1B Weather Transmitter WXT530 Series Vaisala WXT530 Series is a unique series of all-in-one weather instruments that provides 6 of the most important weather parameters: barometric pressure, temperature, relative humidity, rainfall, wind speed and direction. With 6 models available, you can choose measurement parameter combinations to fit your application. Key features include: • Proven sensor technologies used by leading meteorological agencies. • Ultrasonic WINDCAP® wind sensor has no moving parts and provides accurate wind speed and direction measurement. • Acoustic RAINCAP® sensor operates without flooding, clogging, wetting, and evaporation losses and provide maintenancefree operation. • Combined PTU module (barometric pressure BAROCAP®, temperature, and humidity HUMICAP® measurements) uses capacitive measurement for each parameter. •

	Compliance with marine standard IEC60945 and DNV GL approved. • Very low power consumption (typical 3.5mA at 12 VDC) is ideal for battery and solar panel powered system. • Compact design, light-weight, single cabling for all measurements and secure one bolt mounting make installation and deployment easy and fast.
DMT143	G1G1A1A4A0ASX Miniature Dew Point Transmitter Structural Elements DMT143 1 EA Digital Output RS-485 1 EA Analog signal output 4...20mA,0 V error state 1 EA Analog output scaling -80...+20 C Td 1 EA Alarm LED setpoint off 1 EA Process gas air 1 EA 1 bar (abs) Pressure Setting for Optimized Accuracy 1 EA Cable 5.0 m (16.4 ft) with Open Leads 1 EA Standard sintered filter 1 EA No Accessories 1 EA Standard package for DMT143 1 EA Vaisala identity 1 EA Multilingual guide 1 EA
WXT530 4C1B1A2D1B1A	Weather Transmitter WXT530 Series WXT534 Measurement Parameters: Pressure, Temperature, Relative Humidity 1 EA RS-485 Standard ASCII Polled,19200 baud,8,N,1 1 EA 8-pin M12 Male Connector (Bushing and Grounding Accessories Included) 1 EA Standard User Profile 1 EA Shielded 2m Cable, 8-pin M12 Connector in One End 1 EA Mounting Kit and Bird Kit 1 EA WXT User Guide English WXT530 Series 1 EA WXT530 Series Standard Packing 1 EA
DMT340	8W0C1A1XE1A001A1AAB0A0 Sensor for low dew point DMT348 for pressures up to 40 bar 1 EA HMP308 probe (max. Installation depth 149 mm) with 5 m FEP cable 1 EA Td / f, ppm, x, a, rF, T, Td, Td / f atm, Td atm, aNTP 1 EA Display cover 1 EA Standard (24 VDC) 1 EA Analog output output 4 ... 20 mA 1 IO Special scaling Define parameters and scale! 1 EA Channel 2 T (0 ... + 80 ° C) 1 EA Pressure setting 1 bar for max.accuracy 1 EA Metric units 1 EA General application sensor Vaisala DRYCAP®180M 1 EA Stainless steel sintered filter 1 EA Fit body R 1/2 "ISO with drain plug 1 EA Operating instructions DMT340 English 1 EA ISO9001 compliant factory calibration, traceable on NIST 1 EA
WXT530	6D1B2A3A1A1B Weather Transmitter WXT530 Series WXT536 Measurement Parameters: Wind, 1 EA Rain, Pressure, Temp., Relative Humidity RS-485 Standard ASCII Polled,9600 baud,8,N,1 1 EA 8-pin M12 Male Connector (Bushing and Grounding 1 EA Accessories Included) Sensor Heating 1 EA Standard User Profile 1 EA Shielded 10m Cable, 8-pin M12 Connector in One End 1 EA WXT530 Series Standard Packing 1 EA Factory Test Reports WXT530 1 EA
WSP150	Vaisala Surge Protector no Connectors
WXT530	
WXT530 Series Standard Packing	
No Analog Inputs/Outputs WXT530	8-pin M12 Male Connector (Bushing and Groundins Accessories Included) - 1 Each Sensor Heatins 1 Each Standard User Profile - 1 Each Shielded 10m Cable, 8-pin M12 Connector in One End - 1 Each
R73000350	DSP111 SURFACE PATROL WITH DISPLAY AND DIGITAL OPTION
HM46PROBE	Humidity and Temperature Probe ---- The HM46PROBE is a long stainless steel probe for the HM40 Humidity and Temperature Meter. It is an ideal tool for measurement requiring a robust probe structure or in elevated temperatures
M170	
CLB311-230SP	Measuring window fan, 230 VAC, spare part
QML201C	
WMT700	
HMP155	
PTB330	

CMP6	
RG13H	
WID511	
WID512	
DATA LOGGER AND ACCESSORIES PROTECTION PANEL	
MI70 Handheld Measurement Indicator	
R0140442	
Refractometer K-Patents:	sensor SAFE-DRIVE PR-23-SD, range 1,3200-1,5300 nD, indicator DTR-M-GP-AC 220 V (DIM-417)
MMT330	Moisture in Oil and Temperature Transmitter with Remote Probes 7T0F141QQQD113B32DKBDA1 COO: FI MMT337 with small probe for pressure up to 10 bar 1 Each HMP307 Probe with 5m Cable (+180°C) 1 Each aw+T+ppm for Mineral Transformer Oil 1 Each Display Cover 1 Each Power Supply Module with EUR-Power Cord 1 Each Analog Output 4...20mA 1 Each Channel 1 ppm 0..100 1 Each Channel 2 ppm 0..100 1 Each Channel 3 ppm 0..100 1 Each Temperature Range -40...+120C 1 Each Metric Units 1 Each Relay Module 1 Each Analog Output Module 1 Each Conduit fitting NPT1/2 1 Each Outdoor Installation kit (Weather shield) 1 Each HUMICAP180L2 Sensor, Chemically Resistant 1 Each Stainless Steel Filter HM47453 1 Each Swagelok for 12mm Probe 1/2" NPT Thread 1 Each User's Guide MMT330 1 Each USB Service Cable, RJ45 1 Each ISO9001 Compliant Factory Calibration. No Calibration Contract 1 Each
MMT3307T0F141QQQD110B32DKBDA1	
HMD62	RH+T Duct Transmitter, ±1.5 %RH, 4...20 mA COO: FI
A1730098	PMT16C
4418-19	Relative humidity transmitter version without heated probe and without additional temperature probe type HMT337 scale 0 ÷ 100% RH mod. HMT330
WD30	VAISALA WD30 WIND DIGITAL METER FOR ULTRASONIC WIND SENSOR
PTU300	Pressure, Humidity and Temperature Transmitter 12A01C1CBPB1A0A1A1B0B0A Baro-1 module, class B, 500 ... 1100 hPa HMP301 wall mount probe screen cover Internal AC power supply (110... 240 VAC) Analog output 4...20mA Channel 1 T (-40...+60°C) Channel 2: RH 0 ... 100% RH Channel 3 P (500...1100 hPa) Metric units Cable gland M20 x 1.5 Hose barb for 1/8" hose HUMICAP180, Universal Filter: PPS grid with stainless steel mesh Operating Instructions PTU300 ISO9001 factory calibration
RH+T Duct BACnet/Modbus Transmitter	±1.5 %RH HMD65
RH+T Duct Transmitter	±1.5 %RH, 4...20 mA HMD62
Mil-C-26482 For Wav151	
Asm210719sp	
Waa151	
Hmk15b2220b11b	
Hmd110-2c1a1nn	
Wxt530 6c1b2a3d2b1b	

226068	
Hmp3605j5a1a2	
Hmd60y	
Dmt143 G1c1a1b3a1asx	
Gmp222	
Mmt330 8w0f145qcal100a02dmbaa1	
Wxt530 6a1a1a1a1a1b	
Pdt102-P2v	
Hmt330 5m0b121xcax100a11aaba1	
Barometer Cs106	
Humicap180l2	
Hmt360 4d22hhk1a2be5a3k	
Hm70f4a1a0db	
Hmp3605j5a3a2	
Clb311-230sp	
Hm42	
Dmt340 8v0a0a1dxa1a001a1aab0a0 (Dmt348)	
Gmp222 Carbon Dioxide Probe Only (Ppm) For Gmt220 Series Transmitters	
Gmm222	
Mil-C-26482 10 Wire Cable	Für das Viasala Senor modell WAA151: Die angegebene buchse oder mit 20m mit kabel
Dmt 142c3 - (By Dmt143)	
Gmm222 E0n0a4b2a1b Co2 Module	
Hm70 B0b1a0ab	
3a5a1bcx14bbaa1b2	
Aqt420 (10 Pcs)	
Order No:Mmt330 8w0f145qcal100a02dmbaa1 S/N:F0520209	
Wxt530 2c1b2a3d1b1b	
Gmp222 (B0n0 Co2 Probe)	
Dct52	
Mmt330 8v0f101cqa100a02dnbaa1	
Hm70 (B1b1a0aa)	
Hmt330 1a0a101bcab100a01cabaa1	
Dmt242sc	
1434wa	
Hmt 334	

VI-1000	
Hmp233 A2e2a2ee 12b 1 A 3b	
Wxt520 Aad1be31b0	
Hmp46	
Mil-C-26482 6 Wire Cable	Für das Viasala Senor modell WAA151: Die angegebene Buchse oder 20m mit kabel
Aws310	
Hmt331 180a131bcak161b5acabea1	
Hmt330 3e0a001bcab200a0caabaa1	
Rs92dl, No	
Wmt700ba1a0a3e3b1b2	
23028a/74	
Hmw82	
Wxt520	
Hmt360 1d22bce1a2ba5a10	
Hmt330 3e0a001bcac100a01aabaa1	
Hmw60y	
D2540119/D2540118	
Mmt330 2d0f121cqgc123a32dabaa1	
Hmp3608m1a3n2	
Fs11 (More Info Needed)	
Clit311 Obsolete/Replacement Clit321 (Clit321sp - Sp Spare Part)	
Wsp152	
Dmt143-G1g1a1a4a0asx	
Mmt338	
Aqt420	
Dmt142 , Dmt143	
Ptbt210	
Hmp155a-L	
Ptbt110	
Hmm22dcb	
Hmp-50c Temp Amp;Rh	
Dmt3405I0b1a111a1a001a2a0a0	
Hmt120 (Kc0a1f12a2a0z)	
Humicap 335	

Gmp222g0n0
Hmt120 (Ka1a1b12a1a0z)
Wxt530_6c4b1a2b2b1b
Hmt315
Hmp364
Ptb330b
Hmw93 Exproof 20 100 % Rh
Hmt338
Hmt130
Hmp3604e5a3k
Hmp110c15a0c3a0
Hmt330
Wxt1536
Ptb330 B0achaaceb0a0b
Dmt143 N1c1b1a3a0asx
Hmw93 Exproof 0 - 50 ;C
Hm70d0a1a0de
Dmt340
Wxt520-Aab1bc10b0
Hmt330_3g0b001xcag100a0aaccaa1
Hmw92d
Mil-C-26482 For Waa151
Dtr13
Hmt120_Kc1a1b13a6d0z
Hmp_363
Hmt330_1a0a101bcab100a11aabaa1
Hmt3307s1d121dcbx203a0daqbaa1
Hmp360-Ex
Hmt360
Ctt21
Ptb330
8v0f021cpql110c12e3bba1
Y4520066 // Pmt16c Obsolete/No Replacement
Hmp360
Dmt143 Housing Aw24 - 1/2 Quot; Thread
Hmt330/ 8x0b101bcad100a0adngaa1

Dmt143_G1c1b1a3a0asx
Hmp228 Obsolete/Replacement Mmt330
Wac155cb
15778hm
Hmp155a
Dtr503a
Hmp233-C2e7a2aa26x1c3b
8-Pin Male M12 Connector For Hmp 155
Rs92
Hmt331_180a131bcak161b5acaaaa1
Dmt344
Hmt_120y-3m
Hmt335 Replacement
Wa15d7b
Qml201c
Dmt152a1cbb10a010a1a
Hm70b4a1a1db
8v0f121cpql143c12e3bba1
Drd_11a Rain Detector
Hmd70y
222109
Drd11l
Hmt120_Ka1a1b12a1z0z Feuchte- Und Temperatur Mit Integrierter Sonde (Raumfuhler) Hmt120 Mit Lc-Displ
Mmt310f5a5ctd10a52e1g2
Hmt_360 (363) 0 -60;C - 1+1 Supply / Exhaust
Ew-99790-02
Hmp155_A4jc11a0a0a1a0a
Gmt222
Gmt222g0a1b0nxa0a
Hmt337_Hmt330
Hmt330_3g0a001bcax100a0acabaa1
Dmt143-G1c1a1a4a0asx
Rs41
Dmt143

Hmt120 Ka1a1b12a1z0z Feuchte- Und Temperatur Mit Integrierter Sonde (Raumfuhler)
Hmt120 Keine Ic-Dis
Cvim-Conni Pv11.11
Hmt331
Wxt530 Incomplete/Please Provide Complete Order Code
21226b/74
Dmt142
Drw010281sp
Hmt100 Code:A01c102a2a1ab00
Power-1
Hmt310
2000-20r
3a5a1bcx14gbaa1b2
Hmt330 1a0a121bcab100a0aaabaa1
Mi70usadapter+26755
Dmt152
Gm45237sp (Schutzhulse Fur Gmp222)
Hmt120kb1a1e12aoe
Drd11a
Hmp110 V00c2cia0
G1ga1a4a0asx
212792
Dmt3404joboc1dka2a002dia3boao
Ct2614
Hmt330 3e0b101xcax100a0aaacaa1
Hmt3307s0c021xxaa200f0eaabaa1
Wxt-520 Obsolete/Replacement Wxt-530
Hmt330 5n0b001gcalf100a01cgbaa1
219687
Hmd60y 4...20 Ma Outputs, Duct Model Humicapã174; Humidity Amp; Temperature Transmitter
Pdt101
Hmp110
Clt321sp
Dmt3408w0b1b1bea1a111a1abb0a0

Pth330 A0achaaceb0a0b
Wm30 C1ba
Mm70 Hand-Held Moisture Meter For Transformer Oil
Hmt120 Kb1a1b12a1z0z Feuchte- Und Temperatur 3 M Sonden kabel Hmt120 Mit Lc-Display 4...20 Ma, 2-Leit
Hmt330 4h0b001bcak100a0acebaa1
8v0f121cpql140c12e3bba1
Hmt310 5a5a1bcx14bjaa1a2
Dmt242a
Hmt120 Td0axa11a2a0z
Wxt520 Obsolete/Replaced By Wxt530
Hmt120-Ka1a1b11a1a0z
Hmi 36 Is
220614
Hmt 360 (363) 0 ? 100%rh
Rws200
Dmt340 8v0b0a1xxa4a001b1aab0a0
Wxt536
212793
16923wa
16644wa
Ptu300
Hmt330 3f0a001bcag120a01aaba1
Hmp155e1aa1a0b2a1b0a
Dps52
Hmw40y
1433wa
Hm70b4e1a0bb
Hmp155 A2gb13a0a2a1a0a
Hmp235 ? E2a1a1aa32a1a3b Obsolete!! Replaced By Hmt335
Hmt310 3a5a 1bcx 14bbaa 1b2
Hmt3301a0b131ecab200b0aaaba1
Hmt330 7s1d001gxcx103a0daaba1
Hmt3307t2d111xhaa100a2ecpbea1
Dmt340 6r0k1a111a1a001e2d6k0c0

[Hmd60/70](#)

[Wxtptusp](#)